




# LG V10 Side Bumper Replacement

This video shows you how to repair LG V10 side bumper.

Written By: Eric



## INTRODUCTION

<https://www.youtube.com/watch?v=ir2ppUas...>

[video: <https://www.youtube.com/watch?v=ir2ppUaskaw>]

The side bumper of LG V10 can lose varnish or be deformed, broken, scratched after long term of using. The side bumper of LG V10 is also named as steel side rail, side strip and steel side bumper. Follow this repair guide to replace the the LG V10 side bumper.

---



### TOOLS:

- [Phillips #000 Screwdriver](#) (1)
  - [Tweezers](#) (1)
  - [iFixit Opening Tools](#) (1)
  - [adhesive tape 3 mm](#) (1)
-

## Steps:

Step1 Remove back cover and battery;

Step2 Remove back frame and motherboard;

Step3 Remove broken side strips;

Step4 Install new side strips

Step5 Recover the phone.

This document was last generated on 2017-06-21 09:03:38 PM.